


**Поправка к ГОСТ Р 57522—2017 Бережливое производство. Руководство по интегрированной системе менеджмента качества и бережливого производства**

В каком месте	Напечатано	Должно быть
Раздел 4, рисунок 3	 <p>The diagram shows a central box labeled "Инструменты и методы менеджмента качества" (Quality Management Tools and Methods). Above the box is a vertical double-headed arrow. To the right of the box is the text "Организация потока" (Flow Organization) with an arrow pointing right. On the left side, there is a vertical line with an arrow pointing right into the box. On the bottom side, there is a vertical line with an arrow pointing up into the box.</p>	 <p>The diagram shows a central box labeled "Инструменты и методы бережливого производства" (Lean Production Tools and Methods). Above the box is a vertical double-headed arrow. To the right of the box is the text "Организация потока" (Flow Organization) with an arrow pointing right. On the left side, there is a vertical line with an arrow pointing right into the box. On the bottom side, there is a vertical line with an arrow pointing up into the box.</p>

(ИУС № 11 2018 г.)